

CONVERSION TABLE		
64ths	mm	inches
3.0	1.1906	0.0469
3.5	1.3891	0.0547
4.0	1.5875	0.0625
4.5	1.7859	0.0703
5.0	1.9844	0.0781
5.5	2.1828	0.0859
6.0	2.3813	0.0938
6.5	2.5797	0.1016
7.0	2.7781	0.1094
7.5	2.9766	0.1172
8.0	3.1750	0.1250
8.5	3.3734	0.1328
9.0	3.5719	0.1406
9.5	3.7703	0.1484
10.0	3.9688	0.1563
10.5	4.1672	0.1641
11.0	4.3656	0.1719
11.5	4.5641	0.1797
12.0	4.7625	0.1875
13.0	5.1594	0.2031
14.0	5.5563	0.2188
15.0	5.9531	0.2344
16.0	6.3500	0.2500
17.0	6.7469	0.2656
18.0	7.1438	0.2813
19.0	7.5406	0.2969
20.0	7.9375	0.3125
21.0	8.3344	0.3281
22.0	8.7313	0.3438
23.0	9.1281	0.3594
24.0	9.5250	0.3750
25.0	9.9219	0.3906
26.0	10.3188	0.4063
27.0	10.7156	0.4219
28.0	11.1125	0.4375

CONVERSION TABLE		
64ths	mm	inches
29.0	11.5094	0.4531
30.0	11.9063	0.4688
31.0	12.3031	0.4844
32.0	12.7000	0.5000
33.0	13.0969	0.5156
34.0	13.4938	0.5313
35.0	13.8906	0.5469
36.0	14.2875	0.5625
37.0	14.6844	0.5781
38.0	15.0813	0.5938
39.0	15.4781	0.6094
40.0	15.8750	0.6250
41.0	16.2719	0.6406
42.0	16.6688	0.6563
43.0	17.0656	0.6719
44.0	17.4625	0.6875
45.0	17.8594	0.7031
46.0	18.2563	0.7188
47.0	18.6531	0.7344
48.0	19.0500	0.7500
49.0	19.4469	0.7656
50.0	19.8438	0.7813
51.0	20.2406	0.7969
52.0	20.6375	0.8125
53.0	21.0344	0.8281
54.0	21.4313	0.8438
55.0	21.8281	0.8594
56.0	22.2250	0.8750
57.0	22.6219	0.8906
58.0	23.0188	0.9063
59.0	23.4156	0.9219
60.0	23.8125	0.9375
61.0	24.2094	0.9531
62.0	24.6063	0.9688
63.0	25.0031	0.9844